

SOUTH EASTERN RAILWAY

CPO'S OFFICE/GRC

Estt. Srl.No. 95/2016

NO: SERIP-HQ/TRG/737/Manual

Dated : 15-07-2016

To
All Concerned

Sub : Derailment of Locomotive and 3 coaches of Train No. 14266
Dn Dehradun Varanasi Janata Express hauled by Locomotive
No. 11129 WDM3D/AMV at sand hump on loop line No. 1 of
Baccharawan station at Km. 1025/3-5 on Lucknow-Raibareli
section of Lucknow Division of Northern Railway at 09.11
hours on 20.03.2015.

Railway Board's letter No. E(MPP)2016/3/8 dt.09.06.2016 is forwarded for
information, guidance and necessary action.

Encl : As above

(B.N. Soren)

Dy. Chief Personnel Officer(IR)
For Chief Personnel Officer

28/509/337/Manual

⑧

37

Government of India
Ministry of Railways
(Railway Board)

No. E(MPP)2016/3/8

New Delhi, dated 09.06.2016

[Signature]
CSO
May CIVI

SEP
The General Managers,
All Indian Railways

Sub:-Derailment of Locomotive and 3 coaches of Train No. 14266
Dn Dehradum Varanasi Janata Express hauled by
Locomotive No.11129 WDM3D/AMV at sand hump on loop
line No.1 of Baccharawan station at Km. 1025/3-5 on
Lucknow-Raibareli section of Lucknow Division of Northern
Railway at 09.11 hours on 20.03.2015.

Commissioner of Railway Safety, South Central Circle's Final
Report vide Para 9.4 on the above accident has recommended as
under:

"Railway should avoid curtailing the periodical training of loco
pilots which is essential for up-gradation and enhancement of
their driving skill & safety knowledge."

This is brought to the notice of all Railways for information and
necessary compliance.

[Signature]
09/06/16
(Anuradha Singh)
Director(MPP)
Railway Board



3018
09-14/6/16

MR
133

दक्षिण पूर्व रेलवे
SOUTH EASTERN RAILWAY

1-1729
15.06

मुख्य संरक्षा अधिकारी का कार्यालय
गार्डन रीच, कोलकाता - 43.

संख्या /No.50/44/RB/Pt.23

दिनांक : 15.06.2016

To
The Divisional Railway Manager,
S.E. Railway,
ADA, CKP, KGP, RNC.

विषय : Derailment of locomotive and 3 coaches of Train No.14266 On Dehradun Varanasi Janata Express hauled by locomotive No.11129 WDM3D/AMV at sand hump on loop line No.1 of Baccharawan station at Km 1025/3-5 on Lucknow-Raibareli section of Lucknow Division of Northern Railway at 09.11 hours on 20.03.2015.

संदर्भ : Rly. Board's letter No.E(MPP)2016/3/8 dt.09.06.2016.

Railway Board vide letter under reference above has communicated the recommendations of CRS/South Central Circle's final report vide para 9.4 as under:-

"Railway should avoid curtailing the periodical training of loco pilots which is essential for up-gradation and enhancement of their driving skill & safety knowledge."

Board have advised that the same may be brought to the notice of all Zonal Railways for information and necessary compliance. You are requested to note the above recommendation for implementation and necessary compliance. The compliance report may please be sent to this office by 25.06.2016.

APD/Railway

letter to all
units

16/6/16

प्रदीप कुमार

मुख्य संरक्षा अधिकारी

प्रतिलिपी : COM, CME, CEE, CPO - GRC for information and necessary action.

S.D.D. B.
P/S. Circulate.

23/6/16

चक्र/16
Pls. circulate
as desired by
CPO. P/S. 16/6/16