

**Inspection Report of JAA - MURI - RMT section conducted by
Sri. M. M. Pandit, ADRM(OP)/RNC on 25.10.19.**

(Accompanied by Sr. DEE(G), Sr. DSTE, Sr. DME, DEN(E), AOM, AEE(OP)/RNC & ACMS/MURI)

Sl. No.	Observations	Action taken by
JHALIDA (JAA):		
	Staff on duty: Sri. Birendra Kumar Singh, SM/JAA Sri. Binod Kumar Mahato, PM/JAA	Sr.DOM
1.	Station building & ATVM machine: a. SM office is very congested and Ticket Booking counter is also inside SM office. Sometimes passengers enter in SM's office creating hindrance to SM on duty. Booking counter may be shifted elsewhere for smooth and safe train operation to SM on duty. This may be reviewed. b. There is no ATMV machine available at JAA. Keeping in view of crowd of passenger and sales of tickets ATMV machine is to be provided urgently. c. Old furniture to be condemned and new furniture to be procured vice them.	Sr.DOM Sr.DCM Sr.DEN(Co)
2.	Approach Road: Approach road to Station is kucha and water logging reported during rain. It should be concreted.	Sr.DEN(Co)
3.	Platform: a. High level (HL) & PCC surface. b. Tiles of water booth are in broken condition, it should be attended. Proper Drainage system to be provided and it should be covered.	Sr.DEN(Co)
4.	Waiting Hall: a. Waiting hall is to be required to be upgraded. Tiles of waiting hall have been defaced which are required to be replaced. Door of toilet in waiting hall is in broken condition to be repaired. Condition of steel furniture is in bad condition. b. Waiting hall needs whitewashing and sufficient nos. of steel benches to be provided in waiting hall. c. Door of waiting hall is in bad condition to be changed.	Sr.DEN/Co Sr.DCM
5.	Deficiencies in Point & Crossing register: Opening to be increased in Pt. nos. 22B, 17A, 17B, 19A, 27DS and housing to be improved in Pt. Nos. 22B, 28X, 17B, 19A, 19B, 27X.	Sr.DEN(Co)
6.	Lighting facilities: Lighting facility not provided for the approach road. There is scheduled stoppage of Mail/Express train during night hours. Staff and passengers getting difficulties during night hours. Street light facility is to be provided.	Sr. DEE(G)
7.	SWR: English SWR based on SIP number 11340 Alt 'J' and Hindi SWR based on SIP number 11340 Alt 'H' have been brought in force from 01.01.16. Two correction slips have been issued on 21.02.17 and 02.08.18 in English version only. Correction slips in Hindi SWR to be supplied at earliest.	Sr. DOM Sr. DSTE Sr.DSO
8.	Traction SWR: 25 KV AC Traction Diagram board is not as per actual layout. An updated Traction Diagram board to be provided at station.	Sr.DEE(TR) Sr.DOM
9.	Fire Extinguisher: Fire Extinguishers were within due date and Fire Buckets were filled with sand and water properly. A small shed is required to be provided on the fire bucket stands for preserving dry sand during rainy and winter season.	Sr.DEN(Co)
10.	Availability of Toilets: a. Toilet facility is available for Divyang. b. Pay and Use toilet is also available but it remains normally closed as reported because its outsourcing contract for operation and maintenance has not been awarded as yet. Outsourcing of Pay and Use toilet is to be awarded urgently.	Sr.DCM Sr.DEN/Co
11.	Availability of adequate water: a. Source of water: DTW, Open well. b. Tap water available on PF for drinking.	Sr.DEN/Co
12.	General Cleanliness & Housekeeping: a. Cleanliness level of PF, toilet, waiting hall and facade of station to be improved. b. Housekeeping is to be improved. c. Space available in front of station building is to be developed for gardening for beautification of JAA station.	Sr.DEN/Co Sr.DOM

TULIN (THO):		
	Staff on duty: Sri. Sanjeet Kumar, SS/THO Sri. K. P. Agrawal, LR PM/MURI	Sr.DOM
1.	Platform: a. High level PCC platform and chequered tiles fixing work is in progress, work to be completed at the earliest. b. Stairs connecting the platform and station building to be repaired. c. Floor in front of building damaged to be repaired. d. Water leakage from rain gutter of PF shelter and falling on fan is to be attended.	Sr.DEN(Co) Sr.DEE/G
2.	Approach road: Approach road of Station is kucha and water logging reported during rain. It should be concreted.	Sr.DEN(Co)
3.	Waiting hall: Waiting hall wall is heavily seeping, Waiting hall needs whitewashing and repairing of benches also required in waiting hall.	Sr.DEN(Co)
4.	Lighting facility: Electric Wiring has been provided in Public and Divyang Toilets but bulb not provided till date. Lighting facility not provided in new platform shelter. Proper lighting to be ensured in toilets and platforms.	Sr. DEE(G)
5.	SMR office: Housekeeping of SMR office was observed in very bad condition. Old files, old furniture and unused items were found scattered in that room. Old files, broken furniture are to be condemned and disposed off. New furniture to be procured vice condemned furniture.	Sr. DOM
6.	Weighing Machine: An old and defective weighing machine is lying in waiting hall. It should be condemned and disposed off.	Sr. DCM
7.	Fire Extinguisher: Refilling date of Fire Extinguishers expired as it was last filled in 2015. Sufficient nos. of Fire extinguisher is to be kept properly at suitable place and it is to be refilled regularly after stipulated time period.	Sr.DOM
8.	Traction SWR: 25 KV AC Traction Diagram board is not as per actual layout. An updated Traction Diagram board to be provided at station.	Sr.DEE(TR)
9.	General Cleanliness & Housekeeping: a. Cleanliness level of PF, toilet, waiting hall to be improved. b. Housekeeping condition of S&T room is observed in poor condition. Housekeeping is to be improved.	Sr.DCM
10.	Availability of adequate water: a. Source of water: DTW. b. Tap water available on PF for drinking.	Sr.DEN/Co
11.	Availability of Toilets: a. Divyang and general toilets is available.	-do-
Health Unit Muri :		
1.	Moss and dampness appear on the outer wall of the Health unit. Whitewashing required after proper cleaning.	Sr.DEN(Co) ACMS/Muri
2.	Medicines expiry details are displayed on the display board, it is good practice. It should be ensured at HTE, RNC and BANO health units also.	ACMS/Muri
3.	Air Conditioner of ACMS Muri is leaking badly. Water is coming directly inside ACMS room, to be attended.	Sr.DEE/G ACMS/Muri
4.	Seepage noticed on all walls of Health unit. Roof of the health unit to be repaired.	Sr.DEN(Co)
5.	Garden is well maintained inside health unit by ACMS/Muri. But, Garden besides main entrance of health unit is not maintained properly by engineering department. It should be also maintained properly.	Sr.DEN(Co)
RAMGARH (RMT):		
	Staff on duty: Sri. Vaibhav Kumar, SM/RMT Sri. Swapan Dey, Sri. Mangru Mahato and Sri. Dilip Manjhi PM/RMT	Sr.DOM
1.	Platform: a. HL, PCC surface. b. At PF-2 boundary wall broken and vegetation cropped up on PF. Boundary wall is to be repaired and PF to be cleaned.	Sr.DEN/Co Sr.DCM Sr.DOM
2.	Circulating areas: Circulating areas cum parking space to be cleaned and maintained properly.	Sr. DEN(Co)

3.	Drain: Rain water is directly falling from station building, proper drainage pipe to be provided. A cemented hump has been created to cover S&T cables, looking shabby. Cables to be covered properly by cable tray.	Sr.DOM
4.	Waiting hall/Passenger amenities: a. Heavy seepage in 2 nd class waiting hall, booking office and VIP lounge. Seepage from roof inside upper class waiting hall, booking office and VIP lounge to be addressed. b. Light not provided in Divyang toilets, light of 1 st class waiting hall Gents toilets is also not working. Light to be provided at earliest. c. Separated Wet and Dry dustbin to be placed at platform and waiting hall. d. One wheel chair was in defective condition, it should be replaced. e. Cleanliness of booking office was not satisfactory, to be cleaned on regular basis.	Sr. DEN(Co) Sr.DEE(G) Sr.DCM Sr. DOM
5.	Station building: a. An old dressing table is kept in VIP lounge became faded. Dressing table to be polished. b. One Wooden almirah kept in SMR chamber to be condemned as sufficient numbers of steel almirahs has been provided and wooden almirah became discolor. c. Old SM's office to be converted in Staff Rest Room for taking rest of staff.	Sr. DEN(Co) Sr.DOM Sr.DCM
6.	Deployment of Supervisory SMR: After commissioning of Panel interlocking in new building, it is difficult for on duty SMs to monitor Booking office, first class waiting hall and VIP lounge movement. Deployment of Supervisory SMR at RMT is to be reviewed.	Sr. DOM DPO(I/c)
7.	General Cleanliness & Housekeeping: a. Cleanliness level of PF, toilet, waiting hall and circulating area of station to be improved. b. Housekeeping is required to be improved. c. Cleanliness Imprest money is insufficient for station cleaning. Enhancement of cleanliness imprest to be processed.	Sr. DOM
8.	Availability of adequate water: a. Source of water: DTW. b. Tap water available on PF for drinking.	Sr.DEN/Co
9.	Availability of Toilets: b. : Divyang and general toilets is available.	-do-
MAEL (MAEL):		
	Staff on duty: Sri. Mukesh Kumar, SS/MAEL Sri. S. C. Mahato, Sr. CM/MAEL	Sr.DOM
1.	Platform: a. Platform is of Medium level and kucha, PCC to be provided on platform. b. Station name board is in front of the main entrance of New Station building, it should be shifted towards MURI end. c. Benches on Platform are required and gutter of Platform shelter to be changed. d. Approach road of station is kucha and water logging reported, should be concreted.	Sr.DEN(Co) Sr.DCM
2.	Accident Diagram Board: Old Accident diagram board to be replaced with new one and records to be updated.	Sr. DOM
3.	Passenger amenities: a. New fare board and New Time table board in waiting hall cum booking counter to be provided. b. Light of Divyang Toilet are not working, should be attended. c. Staff reported that water supply through water pump from station to railway quarters is not sufficient. It should be improved.	Sr. DCM Sr.DEE/G Sr.DEN/Co
4.	Traction SWR: 25 KV AC Traction Diagram board is not as per actual layout. An updated Traction Diagram board to be provided at station.	Sr.DEE(TR)
5.	Deficiencies in Point & Crossing register: Opening to be increased in Pt. Nos. 102B, 101B. Gauge at ATS to be reduced in Pt. Nos. 102A and Housing to be improved in Pt. Nos. 108B, 103B.	Sr.DEN(Co) Sr. DSTE
6.	General Cleanliness & Housekeeping: d. Cleanliness level of PF, toilet, waiting hall is to be improved. e. Housekeeping is required to be improved.	Sr.DEN/Co Sr.DCM
7.	Availability of adequate water: c. Source of water: DTW. d. Tap water available on PF for drinking.	Sr.DEN/Co
8.	Availability of Toilets: Divyang and general toilets is available.	-do-
BARKIPONA (BRKP):		
	Staff on duty: Sri. Deepak Kumar Singh, LR SM/MURI Sri. Bipin Mandal, PM/BRKP	Sr.DOM


1.	<u>Platform:</u> a. Platform is of Medium level and kucha, PCC to be provided on platform. b. Benches on Platform are required and rain gutter of Platform shelter to be replaced/changed. Doors of toilet are also in defective condition, to be repaired. c. Fare Table board and Time table board in waiting hall cum booking counter to be provided at earliest. d. Additional Tube light and Fan in platform shed to be provided. Mobile charging point also to be provided in platform shed. e. Old station building rooms to be converted in to staff rest room as there is no railway quarters are available at station.	Sr.DEN(Co) Sr. DCM Sr. DEE(G)
2.	<u>Approach road:</u> Approach road of station is kucha and water logging reported, to be concreted.	Sr.DEN(Co)
3.	<u>Passenger Amenities:</u> Public and Divyang toilets have not been handed over to SMR till date. It should be completed and handed over to SMR within a week.	Sr.DEN(Co)
4.	<u>Quality of deep bore well water:</u> SMR reported that bad smells comes in deep bore well water. ACMS/Muri to check the quality of water and submit the report within a week.	ACMS Sr.DEN/Co
	<u>Availability of adequate water:</u> a. Source of water: DTW. b. Tap water not available on PF. Water booth facility is to be provided for drinking water.	Sr.DEN/Co
	<u>Availability of Toilets:</u> a. Divyang and general toilets is available. b. Door of toilets is to be repaired.	-do-
GOLA ROAD (GRE):		
	<u>Staff on duty:</u> Sri. Dhananjay Kumar Roy, SM/GRE Sri. Devesh Kumar, PM/GRE	Sr.DOM
1.	<u>Platform:</u> a. Platform is of high level and surfacing work is in progress, works to be expedite and completed yet the earliest. b. Entry gate of old Waiting hall to be closed and rooms of old station building to be converted in staff rest room. c. Station name board is not provided at entry gate of new station building. d. Lights not provided in public and Divyang toilets. e. Insufficient light at Platforms, more light to be provided on platform. f. On/Off switch of lighting of goods shed is provided towards Muri end of line number 3, it should be shifted in SMs office. g. 04 Steel benches is to be provided in waiting hall. h. Lighting is required in platform shelter.	Sr.DEN(Co) Sr.DEE/G Sr.DCM
2.	<u>Railway Quarter:</u> Water supply in Railway quarters and station is through single bore well. An additional bore well to be explored.	Sr.DEN(Co)
3.	<u>Approach road:</u> Approach road of station is kucha and water logging reported, should be concreted.	Sr.DEN(Co)
4.	<u>Availability of adequate water:</u> a. Source of water: DTW-2. b. Tap water available on PF.	Sr.DEN/Co
5.	<u>Availability of Toilets:</u> Divyang and general toilets is available.	-do-
HARUBRA (HRBR):		
	<u>Staff on duty:</u> Sri. Suman Toppo, SM/HRBR Sri. Ram Gati Yadav, PM/HRBR	Sr.DOM
1.	<u>Platform:</u> a. Platform is of Medium level and kucha, PCC to be provided on platform. b. Insufficient light at Platforms and in front of station building, more light to be provided on platform. c. Rain gutter of Platform shelter to be changed and Gate to be provided in garden of station.	Sr.DEN(Co) Sr.DEE/G
2.	<u>Quarters:</u> There is no provision of electricity in railway quarters, electricity supply to be made available.	Sr. DEE(G)
3.	<u>Deficiencies in Point & Crossing:</u> Opening to be increased in Pt. Nos. 108B and Housing to be improved in Pt. Nos. 115 DS, 114A DS.	Sr.DEN(Co) Sr. DSTE

4.	<u>Availability of adequate water:</u> a. Source of water: DTW. b. Tap water available on PF.	Sr.DEN/Co
5.	<u>Availability of Toilets:</u> Divyang and general toilets is available.	-do-
SONDIMRA (SND):		Sr.DEN(Co)
1.	Platform is of Rail level and surface is kucha.	-do-
2.	Provision of drinking water is not available.	-do-
3.	Seepage of to be attended in station building.	-do-
4.	PF shelter and FOB required at SND.	
BARLANGA (BRLG):		
	<u>Staff on duty:</u> Sri. Ashok Kumar, SM/BLNG Sri. R. K. Munda and Deepak Kumar, PM/BLNG	Sr.DOM
1.	<u>Platform:</u> a. Insufficient light at both ends to Platform, more light to be provided on platform. b. Platform number 1 is of High Level and PCC surface. Platform number 2/3 is also of High Level but surface is Kucha. c. Lighting facility is not provided in new PF shelter.	Sr. DEE(G) Sr.DEN/Co
2.	Water supply in Railway quarters and station is provided by single bore well. An additional bore well to be explored.	Sr.DEN(Co)
3.	<u>Deficiencies in Point & Crossing:</u> a. Opening to be increased in Pt. nos. 107B, 108A. b. Housing to be improved in Pt. Nos. 109A, 101B. c. Gauge at ATS to be reduced in Pt. No. 103B. d. Gap between stretcher bar and bottom of rail to be reduced in Pt. Nos. 109A,108B, 103A.	Sr.DEN(Co) Sr. DSTE
4.	<u>Availability of adequate water:</u> a. Source of water: open well, deep well is required to be provided. b. Tap water available on PF.	Sr.DEN/Co
5.	<u>Availability of Toilets:</u> Divyang and general toilets is available.	-do-
Some other observations:		
1.	Two old camping coaches of track machine one at Muri and another SLF station are laying since long period for POH/Condemnation. This is to be looked in to and to take necessary action.	Sr.DME Sr.DOM
2.	Lots of garbage observed laying in track near RNC station towards Muri Between home and advance starter giving very shabby look. Garbage also observed in track near Argora halt. Yard cleaning is to be ensured.	Sr.DME Sr.DCM Sr.DOM
3.	Condition of boundary wall at PF 1 of Muri is in poor condition giving shabby look. It requires whitewashing. "Sohrai painting" is to be done after whitewashing on boundary wall to give appealing look.	Sr.DEN/Co

No. ADRM(OP)/RNC/Inspection/19

Copy to:

1. DRM/RNC for kind information please.
2. Sr.DOM, Sr.DCM, Sr.DEN/Co, Sr.DEE/G, ACMS/Muri, Sr.DSO, Sr.DEE/TR, Sr.DSTE, Sr.DME, DEN/E & DPO(I/C) for information and necessary action.


(M. M. Pandit)
ADRM(OP) / RNC
Dated: 31.10.2019