Inspection Report of NKM-MURI Section conducted by Sri. Avanish, Sr. DCM/RNC on 02.11.2019.

	Accompanied by DEN(E)/RNC,DEE(OP)/RNC & ACMS /RNC STATION: Namkom (NKM)		
CA	TG : NSG-5		
Staf	f on duty: Sujit Kumar ,SM		
1.	Platform & FOB a. Platform shelter is required at both end of Platform number -1 , 2 &3. b. All slabs of FOB having exposed reinforcement, required for replacement. Shed not available on FOB needs to be provided. c. Cleaning condition of platform needs to be improved, required to be upkeep by Station Imprest.	Sr.DEN(CO) Sr.DOM DCM	
2.	Drinking Water facility: Drinking water facility available, water booths not functional, some taps are found missing from booth.	Sr.DEN(CO)	
3.	SAFETY: a. RCT of M. K. Samanta SMR was overdue from 16.09.2019. b. Housing to be improved in Point nos. 54,X,XDS,72B,74,76A c. At station Foot over bridge, structure bond disconnected from railway track no.02. It should be required for continuity for safety of passenger.	Sr.DOM Sr.DEN(CO) Sr.DEE(TRD)	
4.	Passenger Amenities: a. Piano switch (05A) of 02 nos of ceiling fan broken in waiting hall needs to be replaced. b. Proper tree cutting is required for sufficient at platform, as SST Pole light of PF-01 Obstructed by tree branches. c. Station name board to be provided at approach of entrance station building. d. Old Fare table to be removed and fresh new time table, Fare table and Passenger Amenity details board to be provided.	Sr.DEE(G) Sr.DEN(CO) DCM	
100000	ATION: Tatisilwai (TIS) ATG: NSG-6 Staff on duty: Anand Prakash ,SM		
1.	Platform: a. Some chequered tiles found missing at DN PF, required to be recouped. b. Level of DN PF is medium.	Sr.DEN(CO)	
2.	Passenger amenities: a. 04 Nos water booth is available, but water supply not found. b. Light and fan not found in PF shelter of DN PF. c. More seating arrangement is required at PF-2&3 of UP side of station. d. Flushing cistern found broken in Gents Platform. e. Clear glass of window to be replaced with frosted glass.	Sr.DEN(CO) Sr.DEE(G)	
3.	Cleaning condition of toilet and platform needs to be improved, it should be upkeep by using Station Imprest. Ceiling fan was giving abnormal sound , required to be replaced. Drainage of DN side required to be cleaned.	Sr.DOM Sr.DEE(G)	
4.	Structure hand not provided at station platform shelter required to be provided for	Sr.DEE(TRD) Sr.DEN(CO)	

CAT	TION : Ganga ghat (GAG) G : NSG-6	
	Staff on duty: L.Oraon ,SM	
	Passenger amenities:	Sr.DEE(G)
23	a. One ceiling fan is required in waiting hall.	0.051460
	b. Door of Divyang toilet found broken, needs to be replaced.	Sr.DEN(CO)
1.	c. Water logging noticed at Divyang Toilet, drain needs to be cleared.	DCM
200	d. Water booth available but few taps found missing and broken.	0011
	e. Old Fare table to be removed and fresh new time table , Fare table and Passenger	
	Amenity details board to be provided.	
		Sr.DEN(CO)
	Safety:	Si.ben(ee)
	a. Housing to be improved in Point No.17A,17B,18B,19A,Y,YDS,22A,X,XDS.	Sr.DOM
2.	b.GR correction slip no.125 & 126 not acknowledged by train passing staff.	
	c. Safety meeting of Oct-2019 not conducted.	
	d.Alert advise 06/09 dt.04.10.2019 issued by CSO GRC, acknowledged by only two	
	Staff. Misc:	Sr.DOM
2		31,0011
3.	Cleaning condition of platform, toilet and waiting Hall not satisfactory, it should be	
CT	upkeep by using station imprest.	
CAT	TION : Jonha (JON) G : NSG-6	
	Staff on duty: P. Kispota ,SM	
	Platform:	Sr.DEN(CO)
1.	a. Level of Platform is medium.	
	b. Gutter of PF shelter having sag, outlet pipe is leaking at bend.	
	Passenger Amenities:	Sr.DEN(CO)
	a. Water booth is available and functional, tiles to be provided in water booth.	
	b. Non slippery pathway from ramp of Divyang toilet to PCC PF surface to be provided	Sr.DOM
	c. Old Fare table to be removed and fresh new time table , Fare table and	DCM .
2.	Passenger Amenity details board to be provided.	Den
	d. Cleaning condition of platform needs to be improved, it should upkeep by using	Sr.DEE(G)
	station Imprest.	
	e. Station watering jet pump to be replaced by submersible pump in new building.	
	f. More lighting facility may be provided in stair of station building.	
	Safety:	Sr.DEN(CO
	a. Fire bucket stand to be provided in front of station building.	
3.	b. Guage at ATS to be rectified in point nos.51B	Sr.DOM
	c. GR correction slip no.125 & 126 not acknowledged by train passing staff	
	TION : Kita (KITA)	
CA	rg : NSG-6 Staff on duty: R.L.Tirkey ,SM	
	Platform:	Sr.DEN(CO
1.	Improvement of PF surface found under progress needs to be completed.	
	Passenger Amenities:	Sr.DEN(CC
	a. Water booth not available at platform.	
2	b. Tiolet block on PF-1 has become lower, due to raising of PF, suitable steps to be provided	DCM
2.	c. Old Fare table to be removed and fresh new time table , Fare table and Passenger	
	Amenity details board to be provided.	

	Safety:	
		Sr.DEN(CO)
	Wall around stair well from station building to PF-1 to be provided for safety of passengers.	Sr.DEE(G)
3	b. Guage at ATS to be rectified at point nos X,21.	3.022(0)
3	C. One light point to be provided as station automore stale and for the	1 1
	 One light point to be provided on station entrance stair case for safety of passenger at night. 	
	d. At platform no.01near water tank, flat wire and switch board broken and lying in	
	spare, needs to be disconnected and release.	
	Misc:	Sr.DEN(CO)
4.	a. Pannel room found very congested.	31.0214(00)
	b. Station name Board at PF end to be painted.	Sr.DOM
	ATTON : Silli(SLF) ATG : NSG-6	
	Staff on duty: B.Gope ,SM	
	Platform & FOB	Sr.DEN(CO)
	a. Repairing of PF shelter sheeting to be done at PF-2	SI DEN(CO)
۲.	b. Reinforcement exposed in slabs to be replaced of FOB, one fresh coat paint is also	
	required of FOB structure.	
	Passenger Amenities:	Sr.DEN(CO)
ŀ	a. Whitewashing to be done in toilet at PF-01.	
	b. One tap found leakage in PF-01.	Sr.DEE(G)
	c. Two nos ceiling fan not working at PF-01.	DCM
	 Mobile charging point found broken condition, needs to be replaced. 	
	e. Old Fare table to be removed and fresh new time table , Fare table and Passenger	
-	Amenity details board to be provided.	
	STATION : Muri(MURI) CATG : NSG-5	
	Staff on duty: S.Khan ,SMR	
	Passenger Amenities :	Sr.DEN(CO)
	a. Putty and painting near exhaust fan is required in ladies toilet in waiting hall.	
	 cleaning condition of platform ,toile, and concourse needs to be improved. 	Sr.DME
	c. Broken mesh of toilet drain to be replaced.	
	d. Mosquito net to be provided in window of waiting hall.	
	e. Fresh coat of distemper to be done in enquiry office.	
	f. Roof of Veg & Non-Veg Refreshment Room at PF-2 &3 leaking, needs to be replaced	
	tiled roof with metallic or non-metallic roof, damage false ceiling needs to be repaired.	
	Misc:	Sr.DEN(CO)
	a. Door frame required to be repaired of Toilet Room inside crew lobby, water pipe of	Sr.DEE(G)
	urinal also required to be replaced.	SI.DEE(G)
	b. Name of EI building to be written.	
	c. 02 nos AC provided in EI Pannel room with only local power supply connectivity, uninterrupted power supply may be provided.	
	STATION : Gautamdhara(GATD)	
	CATG : NSG-6	
	Staff on duty: D.Karmali ,SM	
	Platform:	0.00
	Tattorin:	St DEE(C)
1	a.02 Nos octagonal pole light not working at PF-01	Sr.DEE(G) Sr.DEN(CO)

-	Passenger Amenities :	Sr.DEN(CO)
2.	 a. Water connection not provided in water booth, some taps found missing. b. New Divyang Toilet needs to be electrified. c. Old Fare table to be removed and fresh new time table , Fare table and Passenger Amenity details board to be provided. 	Sr.DEE(G)
	Safety:	Sr.DEE(G)
	 a. Battery room exhaust fan not working needs to be replaced. b. NBOX empty/DMF with load 59+1 was stabled on 01.11.2019 at 18.30 Hrs and cleared on 02.11.2019 at 06.12 hrs.but no entry in TSR found. 	Sr.DOM

No.Sr.DCM/RNC/Insp/19

(Avanish) Sr.DCM/RNC

Copy to:i) DRM/RNC for kind information please.

ji) ADRM(O)/RNC for kind information please.

iii) Sr.DEN(CO)/RNC,Sr.DOM/RNC,Sr.DEE(G)/RNC, Sr.DEE(TRD),DEE(OP),
DEN(E)/RNC,ACMS/RNC &DCM/RNC for information and necessary action.

(Avanish) Sr.DCM/RNC