



Report On
SWACHHATA PAKHWADA CAMPAIGN-2025
(01.10.2025-15.10.2025)



KHARAGPUR DIVISION



South Eastern Railway




दक्षिणपूर्व रेलवे
SOUTH EASTERN RAILWAY
KHARAGPUR DIVISION
Date: 06.10.25

REPORT ON SWACHHATA PAKHWADA CAMPAIGN-2025

- ❖ As a part of "SWACHHATA PAKHWADA CAMPAIGN-2025" SWACHH RAILGADI (Clean Train) activities have been undertaken over the division.
- ❖ Various train have been inspected by officers and team of supervisor, linen on train and its storage area has been checked for proper maintenance of cleanliness and hygiene.
- ❖ Intensive inspection of toilet inside of the train has been checked and cleaned.
- ❖ Intensive inspection/Cleaning of trains at washing lines has been also inspected by team of Supervisors.
- ❖ Intensive cleaning of various stations has been also undertaken over the division.
- ❖ Cleaning staffs have been awarded for their best performance during the contract.





Intensive inspection & cleaning of train no :12860 up at SHM station






Intensive Cleaning of toilet of train no Train no 18005 at SANTRAGACHI Station






Intensive Cleaning of Coaches of train no Train no 18005 at SANTRAGACHI Station








Intensive Cleaning of toilets of train no Train no 06081 at SANTRAGACHI Station







Intensive Cleaning of toilets of train no Train no 12834 at SANTRAGACHI Station







Intensive Cleaning of toilets of train no Train no 12810 at SANTRAGACHI Station





Intensive Cleaning of toilets of train no Train no 22807 at SANTRAGACHI Station.





Inspection of linen washing and its storage area at SANTRAGACHI





Inspection of linen washing and its storage area at SANTRAGACHI Station






H8MQ+J9W Bijoy Krishna Girls College, Howrah Railway Station, Howrah, West Bengal 711101, India 🇮🇳

Latitude
22.58379205°
Local 01:43:51 PM
GMT 08:13:51 AM

Longitude
88.33813623°
Altitude 7 meters
Monday, 06.10.2025




H8MQ+J9W Bijoy Krishna Girls College, Howrah Railway Station, Howrah, West Bengal 711101, India 🇮🇳

Latitude
22.58379917°
Local 01:44:12 PM
GMT 08:14:12 AM

Longitude
88.33813315°
Altitude 7 meters
Monday, 06.10.2025

Proper distribution and inspection of Bed roll on Train No:12860, FEED Back from passengers have taken.



H8MQ+J9W Bijoy Krishna Girls College, Howrah Railway Station, Howrah, West Bengal 711101, India 🇮🇳

Latitude
22.58412443°
Local 01:41:16 PM
GMT 08:11:16 AM


Longitude
88.33772752°
Altitude 7 meters
Monday, 06.10.2025




280, Howrah Railway Station, Howrah, West Bengal 711101, India 🇮🇳

Latitude
22.58414964°
Local 01:40:48 PM
GMT 08:10:48 AM

Longitude
88.33766105°
Altitude 7 meters
Monday, 06.10.2025




Balasure, Odisha, India 🇮🇳
23c, Station Rd, Railway Colony, Balasure, Odisha 756001, India
Lat 21.500889° Long 86.920218°
06/10/2025 10:10 AM GMT +05:30



Balasure, Odisha, India 🇮🇳
23c, Station Rd, Railway Colony, Balasure, Odisha 756001, India
Lat 21.500905° Long 86.920223°
06/10/2025 10:15 AM GMT +05:30


Intensive cleaning at BALESHWAR Station




Balasure, Odisha, India 🇮🇳
Fwx9+xqq, Railway Colony, Balasure, Odisha 756001, India
Lat 21.500392° Long 86.919504°
06/10/2025 09:07 AM GMT +05:30




Balasure, Odisha, India 🇮🇳
Fwx9+xqq, Railway Colony, Balasure, Odisha 756001, India
Lat 21.500339° Long 86.919535°
06/10/2025 09:11 AM GMT +05:30




Rag picking on Railway tracks at BALESHWAR Station





Mechanized Cleaning at KHARAGPUR Station





Station Roof cleaning at BAURIA




Intensive Cleaning at GHATSHILA Station




Intensive Cleaning at DOMJUR Station





Intensive Cleaning at BANGRIPOSI Station





Intensive Cleaning at HIJLI Station






Intensive cleaning at SHALIMAR Station





Intensive cleaning at MIDNAPUR Station





Intensive cleaning at SANTRAGACHI Station





Distribution of award to the cleaning staffs for the best performance at BLS

